

ROWE SHORELINE RESTORATION—COMFORT LAKE, WYOMING MN

The Rowe's property is on Comfort Lake. An existing railroad tie sea wall was failing. The wall was falling into the lake, bringing sod and soil from the yard with it. The shoreline required stabilization to prevent further erosion and damage.

The sea wall was removed and replaced with a course of riprap. Above the riprap, a natural buffer was installed using native plants. The riprap will help stop erosion at the water line, while the native plant buffer will help filter water that is running off the yard. The view of the lake from the house will not be impaired.



Partners:

Landowner
Chisago SWCD
Comfort Lake Forest
Lake Watershed
District

Targeted Water:

Comfort Lake

Completion Date:

July 2012

May I Visit?

Yes –you may view this project from the lake only. Please do not enter the property.

