

HULTMAN EROSION CONTROL BMPs

GRASSED WATERWAY AND WASCOS

In 2013 and 2014, a series of erosion control Best Management Practices were installed on Hultman's farm in southern Chisago County. Two grassed waterways were installed in a field that has had erosion problems for many years. A water and sediment control basin (WASCOB) was installed to stabilize a gully on the farm.



Partners:

Chisago SWCD
Landowner

Pollution Reduction:

Total Suspended Solids (TSS): 10.5 tons/yr
Total Phosphorus (TP): 10.0 lbs/yr
(BWSR Pollution Reduction Calculator)

Targeted Water:

South Center Lake

Completion Date:

July 2014

May I Visit?

No. These practices are located on private property and cannot be seen from the road.

