


WEISS SHORELINE RESTORATION—COMFORT LAKE, WYOMING MN

The hillside above the lake on the Weiss property was nearly completely bare. Bare soil on steep slopes is highly prone to erosion. To stabilize the hillside, erosion control blanket was installed and native plants were seeded. Allowing desirable native species to grow on the hillside rather than trying to mow it helps reduce erosion and reduce the amount of fertilizer and other excess nutrients reaching the lake.

Along the shoreline, more erosion control blanket and native seed was installed to help reduce erosion. Native shoreline habitat is also important for native wildlife, such as insects and birds.



Partners:

Landowner
Chisago SWCD
Comfort Lake Forest
Lake Watershed
District

Targeted Water:

Comfort Lake

Completion Date:

July 2012

May I Visit?

Yes –you may view this project from the lake only. Please do not enter the property.

